

[Company](#)
[Products](#)
[Sales](#)
[Support](#)
[Investors](#)

[IP Processing](#)
[Analog Solutions](#)
[WAN Communications](#)
[Product Tree](#)
[Home](#) > [Products](#) > [WAN Communications](#) > [T/E Carrier](#) > [T1/E1 LIUs/Framers](#) > [CX28392/4/5/8](#) > M21105G - 12

M21105G - 12

CMOS OC - 3 to 3.2G QCDR (Rohs Pkg)

MSL:	168 Hours
Package Type:	QFN / MLF
Pin Count:	72
Ordering Multiple:	168
Tube/Tray/Tape:	N/A
Tray/Tube Dwg #:	PD01 - D228 - 181
Operating Temp:	- 40 TO 85 C
Part Status:	Active
Replacement Part:	N/A
Max Reflow Temp:	260C
Pb - free category:	e3
ECCN #:	5A991
Schedule B:	N/A

[Search for another Ordering Part Number](#)

Related Parts

Part	Description	Package	Pin Count	Status
28398 - 16	CN8398KPF	PQFP	N/A	
28398 - 17	CN8398EPF	PQFP	N/A	
28398 - 18	CN8398KBG	BGA	N/A	
28398 - 19	CN8398EBG	BGA	N/A	
28398 - 20	CN8398ECG	CABGA	N/A	
CX28395 - 18	X16 T1/E1/FRAMER	BGA	318	
CX28395 - 19	X16 T1/E1/FRAMER	BGA	318	
CX28395 - 25	16 - Channel T1/E1/J1 Framer IC	PBGA	318	
CX28395 - 26	16 - Channel T1/E1/J1 Framer IC	PBGA	318	
CX28395G - 25	CX28395G - 25 - RoHS -	PBGA	318	
CX28395G - 26	CX28395G - 26 - RoHS -	PBGA	318	
CX28398 - 22	OCTAL T1/E1/J1 FRAMER	MQFP	208	
CX28398 - 23	OCTAL T1/E1/J1 FRAMER	PBGA	272	
CX28398 - 24	OCTAL T1/E1/J1 FRAMER	FPBGA	208	
CX28398 - 25	Octal T1/E1/J1 Framer IC	MQFP	208	
CX28398 - 25P	OCTAL T1/E1/J1 FRAMER	MQFP	208	
CX28398 - 26	Octal T1/E1/J1 Framer IC	PBGA	272	
CX28398 - 27	Octal T1/E1/J1 Framer IC	FPBGA	208	
CX28398 - 27P	OCTAL T1/E1/J1 FRAMER	FPBGA	208	
CX28398G - 25	Octal T1/E1/J1 Framer - RoHS	MQFP	208	
CX28398G - 26	CX28398G - 26 - RoHS -	PBGA	272	
CX28398G - 27	CX28398G - 27 - RoHS -	FPBGA	208	
MW50 - J001 - 001	CX28398TAP Software for Framer CX2839X	EVM	N/A	
MW50 - J001 - 002	Software Support and Maint - CX28398TAP	N/A	N/A	